

## Public Services Report September

- Begin installing concrete around mail boxes where wear and washout have caused unstable footing.
- Trim trees on streets where limbs were too low.
- Install new motor and pump at no. 1 location at main plant. Awaiting SCADA installation on control system. This has been a year long process due to delay in deliveries.
- Replace 3 ea curb stops.
- Replace 4 ea meter heads because of dead batteries.
- Remove power meters from town signs in preparation for sign replacement.
- Replace front wheel bearings on John Deere mower. Done in house.
- Replace chlorine distribution valve in main plant chlorine room.